Federal Aviation Administration – <u>Regulations and Policies</u> Aviation Rulemaking Advisory Committee

Transport Airplane and Engine Issue Area Engine Harmonization Working Group Task 9 – Windmilling Without Oil Task Assignment – Not Available

Recommendation

August 21, 1997 B-T000-ARAC-97-008

BOEING

Mr. Guy Gardner
Associate Administrator for
Regulation and Certification
Department of Transportation
Federal Aviation Administration
800 Independence Avenue, S.W.
Washington, DC 20591

Dear Mr. Gardner:

This is to inform you of the status of the activities concerning JAR 25.903(c)(1), Windmilling Without Oil, and to request closure. On July 6, 1996, Amendment 19 to FAR 33 introduced FAR §33.74 addressing the above activity and revised the test requirements in FAR §33.92, Rotor Locking Test. JAA has released corresponding changes to JAR-E and JAR 25 per letter, R. W. Boning to Y. Morier, 5 August, 1996.

All actions required by the Terms of Reference (ToR), Task #2, for the Power Plant Installation Harmonization Working Group (PPIHWG) have been completed and no further action on the part of the FAA or JAA is required to Harmonize the requirements. PPIHWG recommends that Task #2 be closed and recorded as being completed in all respects. The Transport Airplane and Engine Issues Group (TAEIG) of ARAC concurs with that recommendation and hereby requests closure and recording as recommended.

The members of ARAC TAEIG appreciate the opportunity to participate in the FAA rulemaking process.

Sincerely.

1

Grace

Gerald R. Mack Assistant Chairman, Transport Airplane and Engine Issues Group Aviation Rulemaking Advisory Committee Tele: (425) 234-9964, FAX: (425) 237-4838 B-T000-ARAC-97-008 Mr. Guy Gardner Page 2

CC:

BOEING

Mr. Thaddée Sulocki Joint Aviation Authorities Satunusstraat 10 2130 KA Hoofddorp The Netherlands

Mr. Joseph Hawkins, ARM-1 Department of Transportation Federal Aviation Administration 800 Independence Avenue S.W. Washington, DC 20591 Mr. Stu Miller, ANM-110
Department of Transportation
Federal Aviation Administration
1601 Lind Avenue S.W.
Renton, WA 98055-4056

FAA Action – Not Available